Stein Auto Repair

670 Evans Loaf
Conroe, TX
Phone 281-555-7346

Repair Estimate

Estimate number:	EST-646437
Estimate date:	12/01/2023
Customer:	Matthew Gregory
Phone:	832-555-2086
Insurance claim:	C-1285
Vehicle:	2012 Jeep Cherokee
VIN:	YT4TZRVJ4LXJS2050
License plate:	CM 3465

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$832.36
Left quarter panel	1	$583.24
Front bumper cover	1	$682.25
Body labor	24.1 hrs	$1,637.86
Paint and materials		$710.11
TOTAL		$4,445.82

Appraiser remarks

The front bumper cover is cracked across the center and the radiator support shows bending consistent with a frontal strike at low speed. The hood latch and both headlamp assemblies are damaged, and the grille has lost its mounting tabs. Most of what I see lines up with the impact as described. The shop's lbaor hours fit the repair work outlined, and I found no sign of earlier damgae to this vehicle. Two similar charges submitted on the same day are still being verified before final approval. The repair plan calls for replacing the bumper cover, hood latch, and headlamps, with frame measurements taken before any structural work begins.