Rogers Auto Repair

23623 Robert Isle
League City, TX
Phone 346-555-0366

Repair Estimate

Estimate number:	EST-389101
Estimate date:	2024-03-24
Customer:	Christine Kelley
Phone:	
Insurance claim:	C-1286
Vehicle:	2024 Nissan Altima
VIN:	
License plate:	JMX 588

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$296.81
Hood panel	1	$244.56
Left front fender	1	$264.17
Body labor	9.4 hrs	$636.81
Paint and materials		$305.95
TOTAL		$1,748.30

Appraiser remarks

The rear bumper cover is cracked across the center, the left tail lamp housing is broken, and the trunk lid shows a crease with paint transfer along its lower edge. These marks line up with the rear-end impact described in the claim, and the damage pattern is consistent with a low-speed strike to that corner. The repair plan calls for replacing the bumper cover and tail lamp, straightening and refinishing the trunk lid, and recalibrating the parking sensors. The labor hours listed fit the scope of this work. No prior damage to the vehicle is known from our records or the owner's account, and the patrs and labor lines show no duplicated charges.