Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-376302
Estimate date:	6 May 2025
Customer:	Jacqueline Boyd
Phone:	713-555-5899
Insurance claim:	C-1287
Vehicle:	2012 Jeep Cherokee
VIN:	
License plate:	OIR 464

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$584.94
Hood panel	1	$628.11
Right front door shell	1	$504.93
Body labor	17.1 hrs	$1,160.13
Paint and materials		$667.15
TOTAL		$3,545.26

Appraiser remarks

The rear bumper cover is cracked and the left taillight assembly is broken, with scuffing along the lower quarter panel. Most of this damage lines up with the impact described for a low-speed reversing contact in a pakring lot. The repair plan calls for replacnig the bumper cover, replacing the taillight assembly, refinishing the quarter panel, and a scan for any sensor faults. The labor hours listed fit the scope of this work. The shop's invoice lines show no repeated charges, and nothing on the vehicle or in the file suggests earlier damage to these areas.