# Williams Auto Body

998 Donovan Ford Suite 346
Pearland, TX
Phone 832-555-7510

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-715539 |
| **Estimate date:** | 03/11/2023 |
| **Customer:** | Gregory Martinez |
| **Phone:** | 281-555-2091 |
| **Insurance claim:** | C-1288 |
| **Vehicle:** | 2023 Ford F-150 |
| **VIN:** | D2X8H89MX4WYB7067 |
| **License plate:** | 475 IWK |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Headlamp assembly | 1 | $342.41 |
| Front bumper cover | 1 | $234.72 |
| Hood panel | 1 | $234.18 |
| Body labor | 10.6 hrs | $721.86 |
| Paint and materials | | $310.79 |
| TOTAL | | $1,843.96 |

### Appraiser remarks

The rear bumper cover is cracked across its cneter and the left taillight assembly is broken, with scuffing running along the left quarter panel. The crush pattern and paint transfer line up with the reported low-speed strike in the lot, and nothing in the inspection suggests older damage to this vehicle. The plan is to replace the bumper cover and taillight assembly, refinish the quarter panel, and perform the related alignment checks. The labor hours submitted are in line with this scope of work, and the parts and invoices reviewed show no duplicated or repeated line items. Recommend approval as written.