Mcknight Auto Body

993 Hayes Mills Suite 964
Houston, TX
Phone 713-555-3341

Repair Estimate

Estimate number:	EST-527345
Estimate date:	7 Oct 2023
Customer:	Robin Smith
Phone:	713-555-7063
Insurance claim:	C-1289
Vehicle:	2024 Ford F-150
VIN:	KM1SC9W45UGLU5241
License plate:	676 MRN

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,051.00
Right front door shell	1	$1,219.76
Left front fender	1	$937.37
Body labor	32.0 hrs	$2,178.71
Paint and materials		$1,416.47
TOTAL		$6,803.31

Appraiser remarks

The vehicle shows scraping and a crease along the right rear quarter panel, with the rear bumper cover cracked at its outer edge and the right taillight housing displaced. The damage pattern lines up with a sideswipe during a lane change, and the marks run in a consistent direction along the body. The plan is to replace the rear bumper cover, repair and refinish the quarter panel, and swap the taillight assembly. The labor hours requested fit this scope of work. Nothing in the file points to earlier damage on this vehicle, and the shop invoices show no repeated charges for the same operations.