Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-193590
Estimate date:	18 May 2025
Customer:	Ronald Bradford
Phone:	713-555-8112
Insurance claim:	C-1290
Vehicle:	2021 Kia Sorento
VIN:	RE6LNN42XMWM78757
License plate:	3D Q8237

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$1,351.22
Right tail lamp assembly	1	$1,605.28
Rear bumper reinforcement	1	$1,138.45
Body labor	42.2 hrs	$2,866.68
Paint and materials		$1,499.45
TOTAL		$8,461.08

Appraiser remarks

The rear bumper cover is cracked acorss the center with the lower valance torn free, and the trunk lid shows a crease running toward the left taillight assembly. Most of the visible damage lines up with the impact that was described, and the panel gaps and sensor mounts look consistent with a single rear strike. Labor hours on the proposed repair plan match the work needed to replace the cover, refinish the lid, and recalibrate the praking sensors. The shop billing contains no rpeeated line items, and nothing in the file points to earlier damage on this vehicle. The plan is to replace the bumper cover and taillight, repair and paint the trunk lid, and reset the sensors.