Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-819180
Estimate date:	1 Sep 2024
Customer:	Brad Flores
Phone:	281-555-4606
Insurance claim:	C-1292
Vehicle:	2017 Kia Sorento
VIN:	X6YV781E9YEU54020
License plate:	417 KOY

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,076.00
Front bumper cover	1	$1,301.72
Left front fender	1	$870.25
Body labor	35.2 hrs	$2,396.16
Paint and materials		$1,130.61
TOTAL		$6,774.74

Appraiser remarks

The rear bumper cover is cracked across its cenetr and the left taillight assembly is broken, with scuffing running along the left quarter panel. The pattern of the damage lines up well with the impact that was described, and nothing in the inspection points to earlier body work or prior harm to the vehicle. The repair plan calls for replacing the bumper cover and taillight, refinishing the quarter panel, and a modest amount of labor for alignment of the trunk lid. The labor hours requested are consistent with the work involved, and the invoices submitted show no duplicated or repeated charges. Parts were listed at standard rates. Recommend approval of the estimate as submitted.