Henderson Collision Center

17810 Tanya Terrace Apt. 267
League City, TX
Phone 281-555-6026

Repair Estimate

Estimate number:	EST-441009
Estimate date:	20 Mar 2024
Customer:	Lorraine Allen
Phone:	281-555-8962
Insurance claim:	C-1293
Vehicle:	2024 Honda Civic
VIN:	9RST8RAW6RNWJ7086
License plate:	XNL-977

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$446.83
Right front door shell	1	$511.79
Headlamp assembly	1	$411.02
Body labor	13.4 hrs	$910.82
Paint and materials		$503.05
TOTAL		$2,783.51

Appraiser remarks

Inspection of the rear quarter panel and driver-side door shows scrape marks, a cracked taillight lens, and a bent mriror bracket, all consistent with a sideswipe during a lane change. The damage pattern lines up with the reported impact, and no earlier damage to the vehicle is known. Labor hours for panel straightening, refinishing, and light replacement fit the extent of the damage. Two similar charges posted on the same day are under review with the shop before final approval. Recommended plan: replace the mirror assembly and taillight, repair and refinish the door and quarter panel, then recheck alignment of the door gap.