Jenkins Auto Repair

106 Mcbride Coves
Sugar Land, TX
Phone 281-555-3872

Repair Estimate

Estimate number:	EST-343952
Estimate date:	July 23, 2023
Customer:	Stephanie Hernandez
Phone:	832-555-0094
Insurance claim:	C-1294
Vehicle:	2011 Jeep Cherokee
VIN:	81HMA3X620B6F8980
License plate:	SUM-050

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$712.13
Rear bumper cover	1	$508.39
Rear bumper reinforcement	1	$547.29
Body labor	17.2 hrs	$1,169.69
Paint and materials		$615.37
TOTAL		$3,552.87

Appraiser remarks

The rear bumper cover is cracked and the trunk lid shows a crease along its lower edge, with the left taillight assembly broken at the mounting points. The damage pattern lines up well with the rear-end impact that was reported, and no earlier body damage is recorded on this vehicle. The repair plan calls for replacing the bumper cover and taillight assembly, repairing and refinishing the trunk lid, and checking the rear panel supports for hidden deformation once the trim is removed. The labor hours on the estimate match the scope of work, and the parts and charges on the submitted invoices show no repeated items.