Burgess Collision Center

3287 Katelyn Wall Apt. 226
Pasadena, TX
Phone 346-555-6978

Repair Estimate

Estimate number:	EST-311621
Estimate date:	06/22/2023
Customer:	Dylan Thomas
Phone:	
Insurance claim:	C-1295
Vehicle:	2020 Chevrolet Malibu
VIN:	G5KM0HHU0DN224915
License plate:	GL1 8406

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,288.03
Left quarter panel	1	$731.78
Right front door shell	1	$752.01
Body labor	34.3 hrs	$2,331.57
Paint and materials		$820.83
TOTAL		$5,924.22

Appraiser remarks

Front bmuper cover cracked across the center with the right headlamp assembly broken and the upper radiator support bent. The damage pattern lines up with the reported head-on impact, and no earlier damage to the vehicle is known. Repair plan calls for replacing the bumper cover, headlamp, and radiator support, with a wheel alignment check and a pre-scan of the airbag system. The laobr hours fit the damage shown, and the parts and charges on the invoices show no repeated entries. Recommend approval as submitted, with final supplements only if hidden damage appears during teardown.