White Collision Center

342 Patrick Camp Suite 337
Baytown, TX
Phone 832-555-3303

Repair Estimate

Estimate number:	EST-821350
Estimate date:	April 21, 2025
Customer:	Gregory Phillips
Phone:	
Insurance claim:	C-1296
Vehicle:	2011 Ford F-150
VIN:	W9KN2H2G86UAB1477
License plate:	UEJ-468

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$468.71
Hood panel	1	$357.21
Left front fender	1	$207.88
Body labor	9.1 hrs	$619.67
Paint and materials		$313.55
TOTAL		$1,967.02

Appraiser remarks

The vehicle shows damage consistent with the reported impact while turning left, concentrated on the front driver-side bumper cover, headlamp assembly, fender, and hood leading edge. Crush depth and paint transfer line up with the described contact point, and no prior damage to these panels is known. The proposed repair plan calls for replacing the bumper cover and headlamp, repairing and refinishing the fender, and blending adjacent panels. The labor hours requested fit the scope of this damage. The billing submitted shows no repeated charges for the same operations, and the estimate is recommended for approval as written.