Henderson Collision Center

17810 Tanya Terrace Apt. 267
League City, TX
Phone 281-555-6026

Repair Estimate

Estimate number:	EST-797737
Estimate date:	6 Apr 2024
Customer:	Beth Higgins
Phone:	281-555-1455
Insurance claim:	C-1298
Vehicle:	2014 Honda Civic
VIN:	0LUZHDHE2UY5M2978
License plate:	95FZ9

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,528.52
Right front door shell	1	$1,527.02
Headlamp assembly	1	$1,457.71
Body labor	43.0 hrs	$2,922.77
Paint and materials		$1,481.93
TOTAL		$8,917.95

Appraiser remarks

The vehicle shows front-end damage on the driver's side, consistent with the described impact during a left turn. The bumper cover is cracked near the fog lamp opening, the headlamp assembly is broken at its mounting tabs, and the hood edge is bent where it meets the fender. Damage to the radiator support and the grille frame is reflected in the estimate. A few shallow scratches along the lower door panel may be older than this incident and were noted separately from the crash-related repairs. The repair plan replaces the bumper cover, headlamp, and hood, with refinisihng limited to the affected panels. The labor hours fit the extent of the damage, and the billing lines reviewed contain no repeated charges.