Mason Collision Center

90659 Johnson Forks Apt. 490
Pearland, TX
Phone 346-555-8742

Repair Estimate

Estimate number:	EST-711579
Estimate date:	08/18/2023
Customer:	Kristopher Russell
Phone:	281-555-2412
Insurance claim:	C-1299
Vehicle:	2019 Nissan Altima
VIN:	PGD2JH433TLS69100
License plate:	WGG-316

Estimate details

Description	Qty / Hours	Amount
Trunk lid	1	$1,459.80
Rear body panel	1	$1,321.90
Right tail lamp assembly	1	$1,138.09
Body labor	52.2 hrs	$3,548.06
Paint and materials		$1,709.47
TOTAL		$9,177.32

Appraiser remarks

The rear bumper cover is cracked across its center and the left tail lamp assembly is broken, with scuffing and a bent reinforcement bar consistent with a straight-on rear impact. The trunk lid edge shows matching crush marks, and the damage pattern lines up with the collision as described. No prior damage to this vehicle is known, and the repair plan calls for replacing the bumper cover, tail lamp, and reinforcement bar, followed by refinishing the trunk area and a wheel alignment check. The labor hours listed fit the scope of this damage. The billing submitted shows no repeated charges for the same operations, and the totals reflect the work actually required.