Ellis Auto Repair

83842 Ibarra Gardens
Baytown, TX
Phone 832-555-2784

Repair Estimate

Estimate number:	EST-302294
Estimate date:	February 10, 2023
Customer:	Jason Walls
Phone:	281-555-0597
Insurance claim:	C-1300
Vehicle:	2011 Ford F-150
VIN:	46W3D2Y83BLM87623
License plate:	X12 7WT

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$692.53
Headlamp assembly	1	$581.03
Left quarter panel	1	$403.41
Body labor	22.0 hrs	$1,057.62
Paint and materials		$763.30
TOTAL		$3,497.89

Appraiser remarks

The right rear quarter panel shows a long scrape with paint transfer and a dented edge near the wheel arch, which fits the sideswipe described as occurring during a lane change. The rear bumper cover has a matcihng scuff on its right corner, and the damage pattern runs in a consistent direction across both panels. No earlier damage to the vehicle is known from the file. The repair plan calls for relpacing the bumper cover, blending and refinishing the quarter panel, and reconditioning the door edge. The labor hours on the estimate run somewhat high for this scope and should be reviewed with the shop. Billing records reviweed to date show no repeated charges.