Mason Collision Center

90659 Johnson Forks Apt. 490
Pearland, TX
Phone 346-555-8742

Repair Estimate

Estimate number:	EST-615918
Estimate date:	03/19/2025
Customer:	Jessica Mueller
Phone:	281-555-8973
Insurance claim:	C-1304
Vehicle:	2017 Jeep Cherokee
VIN:	H8VMRNBD8JB9E0022
License plate:	664333

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$358.00
Trunk lid	1	$221.18
Right tail lamp assembly	1	$228.79
Body labor	9.2 hrs	$624.25
Paint and materials		$306.23
TOTAL		$1,738.45

Appraiser remarks

The rear bumper cover is cracked across the center and the left taillight assembly is broken, with the trunk lid showing a crease along its lower edge. The damage pattern lines up well with the impact that was described, and the surrounding panels show no conflicting marks. Repairs will involve replacing the bumper cover and taillight, straightening the trunk lid, and refinishing the rear quarter panel to match. The labor hours assigned to each task look reasonable for the work required. No prior damage to this vehicle is known, and the invoices reviewed contain no reepated charges.