Burgess Collision Center

3287 Katelyn Wall Apt. 226
Pasadena, TX
Phone 346-555-6978

Repair Estimate

Estimate number:	EST-469506
Estimate date:	01/17/2024
Customer:	Jon Johnson
Phone:	832-555-7669
Insurance claim:	C-1305
Vehicle:	2018 Honda Civic
VIN:	35382GS37KMRT0520
License plate:	WL3 C8A

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$591.85
Hood panel	1	$570.21
Front bumper cover	1	$631.19
Body labor	21.7 hrs	$1,475.47
Paint and materials		$701.51
TOTAL		$3,970.23

Appraiser remarks

Right rear quarter panel and rear passenger door show the main crush and deformation, which matches the side impact at the intersection as described. Some scratches on the lower rear bumper look older than this loss and have been noted separately, not included in the repair scope. Parts pricing and paint work are consistent with the damage, and the labor hours shown fit the repairs needed. The invoices reviewed show no repeated charges. Recommended plan: replace the rear door shell, repair and refinish the quarter panel, and recalibrate the rear sensor after reassembly.