Mason Collision Center

90659 Johnson Forks Apt. 490
Pearland, TX
Phone 346-555-8742

Repair Estimate

Estimate number:	EST-330098
Estimate date:	11/17/2023
Customer:	Katie Kennedy
Phone:	281-555-4845
Insurance claim:	C-1308
Vehicle:	2024 Jeep Cherokee
VIN:	YELJTBPN86DPM9012
License plate:	MBD 253

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$457.76
Front bumper cover	1	$593.86
Left quarter panel	1	$500.98
Body labor	14.4 hrs	$980.09
Paint and materials		$412.73
TOTAL		$2,945.42

Appraiser remarks

Inspection of the rear quarter panel and left talilight assembly shows crush and scuffing consistent with a side-to-rear contact while the other vehicle was turning left across the lane. The pattern of deformation lines up with the reported impact, and no older repair marks or prior damage were found on the body or frame during the walk-around. Labor hours for panel replacement, refinishing and light alignment fit the extent of the damage as observed. Two similar charges posted on the same day are currently under review and will be confirmed with the shop before payment. Repair plan: replace the quarter panel, install a new taillight assembly, blend the paint, and recheck the frame measurements after parts are fitted.