Williams Collision Center

75564 King Common Suite 080
Baytown, TX
Phone 281-555-1003

Repair Estimate

Estimate number:	EST-875180
Estimate date:	8 Dec 2023
Customer:	Lisa Bryant
Phone:	346-555-8207
Insurance claim:	C-1309
Vehicle:	2020 Hyundai Elantra
VIN:	JKC3LBDU6EV2W1416
License plate:	HPI 200

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,029.03
Right front door shell	1	$1,492.16
Headlamp assembly	1	$866.42
Body labor	38.5 hrs	$2,620.64
Paint and materials		$1,258.68
TOTAL		$7,266.93

Appraiser remarks

Rear quarter and left rear bumper damage on the vehicle lines up well with the impact described by the driver, who was making a left turn when struck. The pattern of crushed panels, cracked lamp housing and scuffed trim fits a single collision, and nothing visible suggests older damage. The repair plan calls for replacing the bumper cover, straightening the quarter panel, and refinishing the affected area. The labor hours on the estimate are consistent with the work described, and the supplied invoices show no repeated charges for the same parts or tasks.