Ellis Auto Repair

83842 Ibarra Gardens
Baytown, TX
Phone 832-555-2784

Repair Estimate

Estimate number:	EST-639681
Estimate date:	March 20, 2024
Customer:	Dana Washington
Phone:	
Insurance claim:	C-1311
Vehicle:	2016 Chevrolet Malibu
VIN:	TJAMHBKW17LJS0269
License plate:	2-T0729

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,564.24
Left quarter panel	1	$1,077.16
Front bumper cover	1	$1,039.03
Body labor	47.8 hrs	$3,251.53
Paint and materials		$1,554.52
TOTAL		$8,486.48

Appraiser remarks

The vehicle presents with front bumper cover fracture, right headlamp assembly damage, and a cracked grille support on the driver side, consistent with a frontal strike while turning left. Some of the lower radiator support and undercarriage scuffing may not stem from this event, and I have asked the shop to cnofirm before parts are ordered. Two similar line items billed on the same day are under review with the shop. The proposed repair plan of replacing the bumper cover, headlamp, and grille support, with refinishing and a scan for sensor faults, is reasonable, and the lbaor hours submitted fit the damage described. No prior damage to this vehicle is known to me.