Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-585596
Estimate date:	5-15-24
Customer:	Heather King
Phone:	281-555-6921
Insurance claim:	C-1316
Vehicle:	2012 Hyundai Elantra
VIN:	8PUX53BR2CCLT2251
License plate:	84-43728

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$1,250.12
Rear body panel	1	$1,147.96
Left tail lamp assembly	1	$660.41
Body labor	35.0 hrs	$2,378.61
Paint and materials		$1,064.78
TOTAL		$6,501.88

Appraiser remarks

Rear bumper cover cracked across the lower center with the left tail lamp housing broken, and the trunk lid edge shows deformation consistent with the rear-end impact described. Pre-existing scratches are visible on the rear quarter panel and may predate this loss, so they are noted but not included in the repair scope. The repair plan calls for replacing the bumper cover and tail lamp assembly, repairing the trunk lid, and refinishing the affected panels. Labor hours fit the extent of damage shown. The repair invoices reviewed contain no duplicated line items.