Jones Auto Body

738 Jennifer Ports Suite 376
Sugar Land, TX
Phone 713-555-1656

Repair Estimate

Estimate number:	EST-989069
Estimate date:	04/01/2023
Customer:	Michael Gilbert
Phone:	281-555-1314
Insurance claim:	C-1317
Vehicle:	2010 Chevrolet Malibu
VIN:	YTG8K7RY0JL509918
License plate:	653 XIT

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,688.11
Front bumper cover	1	$1,449.63
Left front fender	1	$841.13
Body labor	62.0 hrs	$2,973.80
Paint and materials		$1,680.70
TOTAL		$8,633.37

Appraiser remarks

The front bumper cover is cracked across the center and the upper radiator support has a bent crossmember, with the hood latch and both headlamp brackets displaced. The damage pattern lines up well with the reported frontal impact, and no earlier damage to the vehicle is known from the file. The proposed plan replaces the bumper cover, crossmember, and lamp brackets, with a wheel alignment and a radiator support check. The billing history shows no repeated charges. Labor hours run slightly high for this scope, so I have asked the shop to itemize the hours for each operation before final approval.