Ellis Auto Repair

83842 Ibarra Gardens
Baytown, TX
Phone 832-555-2784

Repair Estimate

Estimate number:	EST-222137
Estimate date:	March 8, 2025
Customer:	Angela Vargas
Phone:	281-555-6440
Insurance claim:	C-1318
Vehicle:	2019 Kia Sorento
VIN:	CTF3NGS37M7YP7043
License plate:	MCO 261

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,318.33
Hood panel	1	$899.61
Front bumper cover	1	$778.20
Body labor	30.5 hrs	$2,074.75
Paint and materials		$1,324.85
TOTAL		$6,395.74

Appraiser remarks

The vehicle presents front-quarter damage on the driver side, consistent with the impact described for a collision during a left-hand turn. The bumper cover is cracked and displaced, the headlamp assembly is broken, and the fender shows a crease running toward the wheel well. Inspection of the radiator support and hood latch found no further structural deformation. The repair plan calls for replacing the bumper cover and headlamp, straightening the fender, refinishing the affected panels, and recalibrating the driver-assist sensor behind the grille. The labor hours listed are in line with the extent of the damage observed. No prior damage to this vehicle is known to me, and the invoices submitted show no repeated charges for the same operations.