Guerrero Auto Body

83242 Brian Turnpike Suite 994
League City, TX
Phone 713-555-7464

Repair Estimate

Estimate number:	EST-231315
Estimate date:	2024-05-17
Customer:	Benjamin Vasquez
Phone:	832-555-3375
Insurance claim:	C-1319
Vehicle:	2012 Nissan Altima
VIN:	K5S0YYTN1AN460294
License plate:	SDL3537

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$484.65
Left quarter panel	1	$586.40
Left front fender	1	$380.68
Body labor	20.4 hrs	$978.51
Paint and materials		$505.18
TOTAL		$2,935.42

Appraiser remarks

The front bumper cover is cracked across the center and the upper radiator support has shifted, which lines up with the frontal impact described. The left headlamp assembly is broken and the hood shows creasing near the leading edge. Damage is confined to the front end, and the parts list reflects a straightforward front-end repair plan: replace the bumper cover, headlamp, and hood, realign the radiator support, and refinish affected panels. Labor hours run slightly above what I would expect for this scope, so I have flagged the line itmes for review with the shop. Nothing I found suggests earlier damage to this vehicle, and the invoices reviewed show no repeated charges for the same work.