Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-871007
Estimate date:	6-16-24
Customer:	Victor Gibson
Phone:	713-555-2481
Insurance claim:	C-1320
Vehicle:	2019 Chevrolet Malibu
VIN:	
License plate:	19H A65

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$532.54
Front bumper cover	1	$339.03
Left front fender	1	$303.10
Body labor	12.5 hrs	$848.58
Paint and materials		$516.97
TOTAL		$2,540.22

Appraiser remarks

Side impact at intersection, driver's door and rear quarter panel. The damage pattern lines up well with the collision as described, and the repair hours quoted are in step with the amount of structural and panel work needed. Plan: replace the front door shell, straighten the rear quarter panel, refinish the affected panels, and recalibrate the side curtain airbag sensor. Nothing in the file points to earlier damage on this vehicle, and the billing records show no duplicated line items. Recommend approval of the estimate as submitted.