Shea Collision Center

75655 Mia Isle Suite 746
Houston, TX
Phone 346-555-1545

Repair Estimate

Estimate number:	EST-333114
Estimate date:	April 4, 2024
Customer:	Natasha Jimenez
Phone:	713-555-2172
Insurance claim:	C-1322
Vehicle:	2013 Ford F-150
VIN:	
License plate:	359-KFXF

Estimate details

Description	Qty / Hours	Amount
Rear bumper cover	1	$946.91
Rear body panel	1	$904.96
Left tail lamp assembly	1	$771.84
Body labor	24.1 hrs	$1,635.52
Paint and materials		$1,135.96
TOTAL		$5,395.19

Appraiser remarks

The rear bumper cover is cracked across the center and the trunk lid shows a crease running toward the left taillight assembly, which fits the rear-end impact described. Both quarter panles have minor paint transfer and the spare tire well is slightly deformed. Several light scratches near the lower bumper edge appear older than this loss and are noted separately from the collision damage. The repair plan calls for replacing the bumper cover and taillight, straightening the trunk panel, and refinishing the affected areas. The labor hours listed are consistent with the work needed, and the parts and charges on the invoice show no repeated entries.