Williams Auto Body

998 Donovan Ford Suite 346
Pearland, TX
Phone 832-555-7510

Repair Estimate

Estimate number:	EST-630345
Estimate date:	01/17/2025
Customer:	Rebecca Hutchinson
Phone:	832-555-7683
Insurance claim:	C-1323
Vehicle:	2011 Jeep Cherokee
VIN:	YVE8BG4J7DR0E9386
License plate:	KUL-337

Estimate details

Description	Qty / Hours	Amount
Rear bumper cover	1	$354.07
Trunk lid	1	$340.66
Rear bumper reinforcement	1	$206.09
Body labor	9.4 hrs	$641.47
Paint and materials		$374.64
TOTAL		$1,916.93

Appraiser remarks

The rear bumper cover is cracked and displaced, with the trunk lid edge and both taillight assemblies showing impact deformation consistent with the reported rear-end collision. Damage to the quarter panel and the rear crossmember is limited and follows the energy path expected from this type of strike. Nothing in the vehicle's codnition suggests prior unrepaired damage in these areas. The proposed plan replaces the bumper cover, taillight assemblies and trunk lid, and includes straightening the crossmember bracket and refinishing the affected panels. The labor hours requested match the scope of these repairs, and the parts list shows no duplicated line items. Recommend approval as submitted, with supplements only if hidden damage appears during teardown.