Williams Collision Center

75564 King Common Suite 080
Baytown, TX
Phone 281-555-1003

Repair Estimate

Estimate number:	EST-722907
Estimate date:	10 Jul 2025
Customer:	Kaylee Johnson
Phone:	346-555-1648
Insurance claim:	C-1324
Vehicle:	2016 Honda Civic
VIN:	
License plate:	Y69-05P

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,254.25
Headlamp assembly	1	$911.02
Hood panel	1	$978.68
Body labor	29.4 hrs	$2,002.20
Paint and materials		$1,420.31
TOTAL		$6,566.46

Appraiser remarks

Vehicle was struck on the front driver-side quarter while the other car was turning left across its path. The damage visible on the front bumper cover, driver-side headlamp assembly, and fender is consistent with that type of impact, and the pattern of contact points lines up with the account given. No prior damage to this vehicle is known, and the paperwork reviewed shows no repeated charges for the same parts or labor. Proposed repairs call for replacing the bumper cover, headlamp, and fender, plus refinishing and a radiator support check. The labor hours assigned to each operation fit the extent of the damage, and the plan is reasonable for a vehicle in this condition.