Williams Collision Center

75564 King Common Suite 080
Baytown, TX
Phone 281-555-1003

Repair Estimate

Estimate number:	EST-483022
Estimate date:	9 Sep 2024
Customer:	Lindsey Martinez
Phone:	713-555-7223
Insurance claim:	C-1325
Vehicle:	2013 Hyundai Elantra
VIN:	
License plate:	DH 50540

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$529.46
Hood panel	1	$418.90
Left quarter panel	1	$342.02
Body labor	14.8 hrs	$1,006.47
Paint and materials		$579.08
TOTAL		$2,875.93

Appraiser remarks

Inspection of the front end shows damage consistent with the reported head-on impact, including the bumper cover, grille, hood leading edge, and both headlamp assemblies. The pattern of crush and displacement lines up with the stated collision, and the body shop's labor hours are reasonable for the repairs listed. Billing records were reviewed and show no duplicated line items. A few minor scratches on the lower door panels appear older than this loss and are noted separately so they are not included in the repair scope. Recommended plan: replace the bumper cover and headlamps, repair the hood and grille support, refinish affected panels, and recalibrate the forward radar sensor before release.