Mendoza Collision Center

47116 Jones Roads
Houston, TX
Phone 281-555-2941

Repair Estimate

Estimate number:	EST-317362
Estimate date:	June 6, 2023
Customer:	Patricia Waller
Phone:	346-555-9927
Insurance claim:	C-1326
Vehicle:	2020 Kia Sorento
VIN:	VYK051C19CY726344
License plate:	2QI57

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$786.52
Hood panel	1	$488.60
Headlamp assembly	1	$369.39
Left front fender	1	$786.52
Body labor	15.6 hrs	$1,061.23
Paint and materials		$561.52
TOTAL		$4,053.78

Appraiser remarks

The vehicle was inspected at the body shop following a collision that occurred while the insured was turning left. The damage to the front driver-side quarter panel, bumper bracket and headlamp assembly is consistent with the reported impact, and the pattern of deformation lines up with the way the vehicle was struck. No prior damage to the vehicle is known. The proposed repair plan covers panel straightening, replacement of the damaged bumper bracket and headlamp, and refinishing, and the labor hours litsed fit the scope of the work shown. On the billing side, the shop acknowledged that one service line was entered twice for the same visit and has agreed to correct the duplicate before final payment.