Tucker Collision Center

627 Tina Place Apt. 699
Houston, TX
Phone 713-555-6272

Repair Estimate

Estimate number:	EST-464514
Estimate date:	June 2, 2024
Customer:	Denise Jacobs
Phone:	832-555-8815
Insurance claim:	C-1329
Vehicle:	2018 Nissan Altima
VIN:	EXDMA4E62VGGV1686
License plate:	7-Q3207

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$526.37
Front bumper cover	1	$311.42
Left front fender	1	$343.60
Hood panel	1	$526.37
Body labor	12.5 hrs	$847.90
Paint and materials		$551.38
TOTAL		$3,107.04

Appraiser remarks

The front bumper cover shows creased deformation and the upper grille bracket is cracked, consistent with a low-speed frontal contact. However, the damage pattern sits on the rear quarter panel and at a lower height than the described impact would produce, so the reported mechanism does not fully explain what was found. The repair plan calls for replacing the bumper cover, the grille bracket and the affected quarter panel, with refinishing and a headlamp alignment check. The labor hours listed fit the scope of this work. No prior damage to this vehicle is known from our records. Separately, the shop's ivnoice shows the same service billed twice on one date, and the provider has acknowledged the second entry was a repeat, so that line should be corrected before payment.