Shea Collision Center

75655 Mia Isle Suite 746
Houston, TX
Phone 346-555-1545

Repair Estimate

Estimate number:	EST-819053
Estimate date:	June 11, 2024
Customer:	Kari Gonzalez
Phone:	713-555-2172
Insurance claim:	C-1331
Vehicle:	2023 Toyota Camry
VIN:	K10DH94C5KPDN3873
License plate:	ZBE1563

Estimate details

Description	Qty / Hours	Amount
Trunk lid	1	$238.66
Right tail lamp assembly	1	$187.26
Rear body panel	1	$193.49
Body labor	8.9 hrs	$604.84
Paint and materials		$309.87
TOTAL		$1,534.12

Appraiser remarks

The rear bumper cover is cracked across its center with the left tail lamp housing broken, and the trunk lid shows a crease consistent with the reported rear impact. The damage pattern lines up well with how the collision was described. The repair plan calls for replacing the bumper cover and tail lamp assembly, repairing the trunk lid, and refinishing the affected panels. The labor hours requested fit the extent of the damage, and the parts and charges on the invoices show no repeated entries. Nothing in the file suggests earlier damage to this vehicle in these areas.