King Auto Repair

184 Rodriguez Mews
Pearland, TX
Phone 346-555-0482

Repair Estimate

Estimate number:	EST-452960
Estimate date:	February 27, 2023
Customer:	Lisa Moore
Phone:	713-555-5066
Insurance claim:	C-1332
Vehicle:	2012 Chevrolet Malibu
VIN:	4JB74EYB1DY360487
License plate:	9G 3K7YOW

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$805.98
Right front door shell	1	$684.91
Headlamp assembly	1	$549.76
Body labor	20.2 hrs	$1,376.99
Paint and materials		$552.78
TOTAL		$3,970.42

Appraiser remarks

The vehicle was inspected at the body shop following a sideswipe that occurred during a lane change. The damage is located along the right rear quarter panel and rear door, with scrape marks and a dented fender edge that line up well with the described contact. A few older scratches are also visible near the bumper, which may predate this incident and have been noted separately. The repair plan calls for replacing the rear door skin, straightening the quarter panel, and refinishing the affected areas. The labor hours listed fit the scope of this damage, and the invoice lines show no repeated charges. Recommended repairs are approved as written, with the older marks excluded from the scope of this claim.