Jones Auto Body

738 Jennifer Ports Suite 376
Sugar Land, TX
Phone 713-555-1656

Repair Estimate

Estimate number:	EST-534638
Estimate date:	08/24/2024
Customer:	Ann Wilson
Phone:	346-555-2044
Insurance claim:	C-1334
Vehicle:	2020 Chevrolet Malibu
VIN:	74RAUJJ51T6XU8776
License plate:	OWF-962

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$967.84
Front bumper cover	1	$805.44
Left front fender	1	$839.22
Body labor	29.5 hrs	$2,004.99
Paint and materials		$1,281.88
TOTAL		$5,899.37

Appraiser remarks

Inspection of the vehicle shows scraping and paint transfer along the right rear quarter panel, a cracked rear bumper cover end, and a dented rear door skin with a broken side marker lens. The damage pattern lines up well with a sideswipe during a lane change, and nothing observed points to a different cause. The repair plan calls for replacing the bumper cover, refinishing and blending the quarter panel and door, and swapping the marker lens, with the labor hours sized to that scope. No prior damage to this vehicle is known from our records or the owner's account. The invoices sbumitted so far show no duplicated or repeated charges.