Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-415509
Estimate date:	30 Jun 2025
Customer:	Theresa Allen
Phone:	346-555-1809
Insurance claim:	C-1337
Vehicle:	2018 Ford F-150
VIN:	
License plate:	826 LSR

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$839.09
Headlamp assembly	1	$1,001.48
Hood panel	1	$760.90
Body labor	25.0 hrs	$1,700.14
Paint and materials		$986.81
TOTAL		$5,288.42

Appraiser remarks

Vehicle inspected at the shop following a side impact at an intersection. The damage to the driver's side door, quarter panel and rocker area is consistent with the reported collision, and the pattern of crushing and paint transfer lines up with the described angle of contact. No prior damage to this vehicle is known to us, and nothing visible suggests older repairs. The proposed plan replaces the door shell, repairs the quarter panel, and refinishes the affected panels. The labor huors requested fit the socpe of this work. The invoices submitted show no repeated charges for the same operations.