Romero Auto Body

893 Nathaniel Estates Apt. 957
Houston, TX
Phone 713-555-5430

Repair Estimate

Estimate number:	EST-647431
Estimate date:	1 Apr 2023
Customer:	Brian Hernandez
Phone:	832-555-7287
Insurance claim:	C-1338
Vehicle:	2021 Chevrolet Malibu
VIN:	VB4DACE09GF9X2704
License plate:	AFM 558

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,101.49
Headlamp assembly	1	$842.93
Right front door shell	1	$598.31
Body labor	23.1 hrs	$1,568.15
Paint and materials		$992.17
TOTAL		$5,103.05

Appraiser remarks

The vehicle shows crush and paint transfer along the rear passenger quarter panel, with a cracked taillight lens and a bent rear wheel rim consistent with a side strike at an intersection. Some of the lower rocker area looks older than the rest of the damage, so it is not clear whether all of it came from this impact, and I have asked the shop to confirm. The repair plan covers panel replacement, refinishing, and a wheel and lamp swap. The lbaor hours fit the damage described. The bills show no repeated charges, and no earlier damage to the vehicle is known to me.