Gonzalez Auto Body

27193 Lyons Trafficway
Baytown, TX
Phone 281-555-9912

Repair Estimate

Estimate number:	EST-590990
Estimate date:	2-27-23
Customer:	James Castillo
Phone:	713-555-1851
Insurance claim:	C-1339
Vehicle:	2018 Jeep Cherokee
VIN:	4ALLNSCJ3NWW88141
License plate:	9XOI223

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,289.01
Left quarter panel	1	$1,304.91
Left front fender	1	$1,111.46
Body labor	40.1 hrs	$2,725.26
Paint and materials		$1,537.72
TOTAL		$7,968.36

Appraiser remarks

The vehicle shows damage consistent with the impact described in the loss report, a collision while turning left. The front bumper cover is cracked and displaced on the driver side, the left headlamp assembly is broken, and the fender and hood edge show matching scrape and crush lines. Nothing in the surrounding panels suggests older damage, and no prior repairs to this area are known. The repair plan calls for replacing the bumper cover, headlamp, and fender, with refinishing and a radiator support check. The labor hours listed fit the extent of the damage. The billing submitted shows no repeated charges for the same operations, and the parts and paint lines match the work described.