Freeman Collision Center

4948 Zachary Field Apt. 367
Sugar Land, TX
Phone 346-555-7701

Repair Estimate

Estimate number:	EST-249337
Estimate date:	4 Dec 2023
Customer:	Colleen Jones
Phone:	281-555-3182
Insurance claim:	C-1340
Vehicle:	2011 Ford F-150
VIN:	7LJ0T9TWXATX41889
License plate:	1N 91667

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$537.99
Right front door shell	1	$534.79
Left quarter panel	1	$284.36
Body labor	15.2 hrs	$1,033.24
Paint and materials		$559.10
TOTAL		$2,949.48

Appraiser remarks

The rear bumper cover is cracked across its lower center and the left taillight assembly is broken, with scuffing and paint tarnsfer on the rear quarter panel. The damage lines up well with the impact that was described, and the pattern shows nothing that points to a different event. The plan is to replace the bumper cover, the taillight assembly, and the quarter panel, followed by refinishing and a sensor recalibration. The labor hours requested are in line with the work involved. Nothing in the vehicle's history suggests earlier damage to these areas, and the invoices submitted reflect a single set of charges with no duplicated line items.