Nolan Auto Body

158 Dickson Summit
Pearland, TX
Phone 281-555-2260

Repair Estimate

Estimate number:	EST-652490
Estimate date:	01/10/2024
Customer:	Stephanie Olson
Phone:	832-555-8727
Insurance claim:	C-1341
Vehicle:	2014 Jeep Cherokee
VIN:	UERREP9X6VPP13600
License plate:	41UR383

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$687.94
Front bumper cover	1	$456.79
Hood panel	1	$433.11
Body labor	13.7 hrs	$933.30
Paint and materials		$445.48
TOTAL		$2,956.62

Appraiser remarks

Inspection of the vehicle shows scraping and deformation along the right rear quarter panel, with a cracked tail lamp lens and a scuffed rear bumper cover on the same side. The pattern of contact is consistent with the sideswipe described during a lane change, and the damage runs in a continuous line from the bumper to the door sill. Repair will involve replacing the bumper cover, the tail lamp assembly, and straightening the quarter panel with refinishing to match. The labor hours on the estimate fit the scope of this work. Nothing in our records or the owner's history points to earlier damage in these areas, and the invoices submitted contain no repeated charges.