# King Auto Repair

184 Rodriguez Mews
Pearland, TX
Phone 346-555-0482

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-701809 |
| **Estimate date:** | July 2, 2023 |
| **Customer:** | Samuel Fuller |
| **Phone:** | |
| **Insurance claim:** | C-1342 |
| **Vehicle:** | 2018 Kia Sorento |
| **VIN:** | 6TL6XPUS6Y4KD6265 |
| **License plate:** | GGY 9238 |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Rear bumper cover | 1 | $1,401.28 |
| Right tail lamp assembly | 1 | $1,211.75 |
| Trunk lid | 1 | $712.09 |
| Body labor | 29.0 hrs | $1,971.73 |
| Paint and materials | | $1,033.38 |
| TOTAL | | $6,330.23 |

### Appraiser remarks

The rear bumper cover is cracked arcoss the center and the turnk lid shows a crease running toward the left taillight. Most of the damage lines up with the reported rear-end impact, and the repair hours and parts listed fit what is visible on the vehicle. A few light scratches near the tailgate look older than this incident and have been noted separately rather than included in the scope. The repair plan calls for replacing the bumper cover, straightening the trunk lid, refinishing the affected panels, and replacing the left taillight assembly. Shop charges appear in a single consistent set with no repeated line items.