Mcknight Auto Body

993 Hayes Mills Suite 964
Houston, TX
Phone 713-555-3341

Repair Estimate

Estimate number:	EST-720056
Estimate date:	26 Oct 2024
Customer:	Susan Ellis
Phone:	346-555-9735
Insurance claim:	C-1343
Vehicle:	2011 Jeep Cherokee
VIN:	6617RVWJ31M0V3604
License plate:	HV6 9474

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,685.27
Left front fender	1	$1,700.37
Left quarter panel	1	$1,326.19
Body labor	35.6 hrs	$2,418.41
Paint and materials		$1,224.55
TOTAL		$8,354.79

Appraiser remarks

Inspection of the rear quarter panel and rear door shows a continuous scrape pattern running aolng the passenger side, consistent with a sideswipe during a lane change. Most of the damage lines up with the impact as described. A few older scratches sit near the rear bumper and may predate this incident, so they are noted separately and excluded from the repair scope. The repair plan calls for blending and refinishing the door and quarter panel, replacing the damaged mirror housing, and reconditioning the bumper cover edge. The labor hours requested fit the extent of the work. The invoice shows no repeated charges for the same operations, and the parts listed match the repair plan.