Smith Collision Center

4687 James Forge Apt. 980
Baytown, TX
Phone 713-555-0978

Repair Estimate

Estimate number:	EST-405505
Estimate date:	10-26-23
Customer:	Karen Melendez
Phone:	832-555-8099
Insurance claim:	C-1344
Vehicle:	2024 Honda Civic
VIN:	9EX54GK47UGU47113
License plate:	785-WRQ

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$931.59
Headlamp assembly	1	$886.56
Right front door shell	1	$581.36
Body labor	26.7 hrs	$1,812.90
Paint and materials		$1,137.17
TOTAL		$5,349.58

Appraiser remarks

The rear bumper cover shows fresh cracking and displaced mounting tabs, and the left quarter panel has a deep scrape running toward the wheel arch. Some of the marks on the loewr door are a few old scratches that may be older than this crash, so the shop should confirm which areas were touched in this impact. The proposed plan is to replace the bumepr cover, repair and refinish the qaurter panel, and blend the adjacent door. The repair labor hours fit the damage described, and the parts and paint charges show no repeated entries. Final supplements should be reviewed once the teardown is complete.