Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-477407
Estimate date:	5-31-23
Customer:	Leonard Reed
Phone:	346-555-8499
Insurance claim:	C-1345
Vehicle:	2015 Kia Sorento
VIN:	BCEGY5EKXVJSW2114
License plate:	HFW-514

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$548.06
Right front door shell	1	$628.16
Hood panel	1	$457.80
Body labor	24.8 hrs	$1,188.87
Paint and materials		$650.05
TOTAL		$3,472.94

Appraiser remarks

The front bumper cover is cracked across the center, with the grille tabs broken and the upper radiator support bent slightly rearward. The hood latch and both headlamp brackets show stress marks that match a low-speed frontal contact. Most of the damage lines up with the impact as described. The repair plan calls for replacing the bumper cover and grille, straightening the radiator support, and refinishing the hood. The labor hours on the estimate run a little high for this scope, so the shop should be asked to justify them line by line. The invoices submitted show no repeated charges. No prior damage to the vehicle is known from the file or the owner's records.