Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-938739
Estimate date:	5-1-24
Customer:	Michelle Young
Phone:	713-555-8514
Insurance claim:	C-1347
Vehicle:	2015 Nissan Altima
VIN:	FXZJKH1S13PK40269
License plate:	219U8

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,496.81
Left front fender	1	$787.13
Right front door shell	1	$1,079.24
Body labor	29.2 hrs	$1,985.34
Paint and materials		$1,040.76
TOTAL		$6,389.28

Appraiser remarks

Front bumper cover cracked and displaced on the driver side, with the upper radiator support bracket bent and the hood latch assembly distorted. The headlamp assembly on that side is cracked, and the grille mounting tabs are broken. The damage pattern lines up with the reported frontal contact, and the crush depth stays within what a low-speed impact would produce. No prior damage to this vehicle is known or recorded. The repair plan calls for replacing the bumper cover, headlamp, grille and latch, followed by a radiator support alignment and refinish of the front end. The labor hours submitted fit the scope of this work, and the supplement invoices contain no duplicated line items.