Hall Auto Repair

1823 Joanna Harbor
Katy, TX
Phone 713-555-3435

Repair Estimate

Estimate number:	EST-234871
Estimate date:	2025-01-08
Customer:	Colleen Jones
Phone:	281-555-3182
Insurance claim:	C-1348
Vehicle:	2022 Nissan Altima
VIN:	6UBYHB972KHKZ2115
License plate:	4AE 610

Estimate details

Description	Qty / Hours	Amount
Rear bumper cover	1	$343.08
Left tail lamp assembly	1	$362.02
Rear body panel	1	$211.14
Body labor	8.0 hrs	$543.96
Paint and materials		$405.10
TOTAL		$1,865.30

Appraiser remarks

The rear bumper cover is cracked and pushed inward on the driver side, with the trunk lid edge and right tail lamp assembly showing impact deformation that lines up with a rear-end strike. Reinforcement bar bracing and the rear panel behind the bumper will be replaced, and the tail lamp will be swapped out rather than repaired. The labor hours written into this estimate are in line with the extent of the damage, and the repair plan follows standard procedure for this kind of impact. Nohting on the vehicle suggests older damage in the same area, and the repair invoices on file do not show duplicate charges for the same work.