Romero Auto Body

893 Nathaniel Estates Apt. 957
Houston, TX
Phone 713-555-5430

Repair Estimate

Estimate number:	EST-860280
Estimate date:	18 Jan 2023
Customer:	Kevin Clayton
Phone:	346-555-7933
Insurance claim:	C-1351
Vehicle:	2011 Hyundai Elantra
VIN:	SZH52RAHXSCTL7165
License plate:	LAK 415

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$332.18
Left tail lamp assembly	1	$332.57
Rear bumper reinforcement	1	$259.34
Body labor	10.8 hrs	$732.17
Paint and materials		$319.79
TOTAL		$1,976.05

Appraiser remarks

The rear bumper cover is cracked across its center section, with the left tail lamp assembly broken and the trunk lid skin dented near the latch. Crush and scuff marks on the lower bumper bar line up with the reported rear-end impact, and the damage pattern is consistent with the account given. Nothing I found suggests prior damage to this vehicle, and no earlier repairs are on record. The proposed labor hours are reasonable for replacing the bumper cover and lamp, refinishing the lid, and recalibrating the parking sensors. The supplied invoices show no duplicated charges, so the estimate is supported as written.