Ellis Auto Repair

83842 Ibarra Gardens
Baytown, TX
Phone 832-555-2784

Repair Estimate

Estimate number:	EST-688549
Estimate date:	July 12, 2024
Customer:	Justin Middleton
Phone:	346-555-3677
Insurance claim:	C-1353
Vehicle:	2023 Hyundai Elantra
VIN:	86YLTDJH7837R0602
License plate:	67F-NTNT

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$787.38
Rear body panel	1	$796.05
Rear bumper cover	1	$582.74
Body labor	22.8 hrs	$1,547.16
Paint and materials		$807.12
TOTAL		$4,520.45

Appraiser remarks

The rear bumper cover is cracked and the trunk lid shows a crease along its left edge, with the tail lamp assembly broken on the driver side. The damage pattern matches the rear-end impact as described, and the surrounding panels show no signs of a separate or older event. The repair plan calls for replacing the bumper cover and lamp, straightening the trunk lid, and refinishing the affected areas. The estimated labor hours are consistent with this scope of work, and the parts listed correspond to what the visible damage requires. No prior damage to this vehicle is on record, and the invoices reviewed contain no duplicated line items.