Williams Collision Center

75564 King Common Suite 080
Baytown, TX
Phone 281-555-1003

Repair Estimate

Estimate number:	EST-925835
Estimate date:	2 Jul 2024
Customer:	Zachary Arnold
Phone:	713-555-5123
Insurance claim:	C-1354
Vehicle:	2024 Honda Civic
VIN:	YR086UX76RMZE2304
License plate:	ZLT 980

Estimate details

Description	Qty / Hours	Amount
Right tail lamp assembly	1	$1,515.43
Trunk lid	1	$1,592.76
Rear body panel	1	$1,441.62
Body labor	54.1 hrs	$2,594.83
Paint and materials		$2,010.60
TOTAL		$9,155.24

Appraiser remarks

The rear bupmer cover is cracked across the center with the lower valance torn loose, and the tail lamp assembly on the driver side is broken. The trunk lid shows a crease at the lower edge, and the rear panel brace has bent slightly, consistent with the impact described. No earlier damage to the vehicle is known, and the prior records reviewed show nothing that conflicts with this loss. The plan is to replace the bumper cover, valance, and lamp assembly, repair the trunk lid, and straighten the brace. The labor hours on the estimate run a little high for this scope, so I recommend a line-by-line review before approval. The billing history shows no repeated charges.