Hoffman Auto Body

280 Aguilar Drive
Conroe, TX
Phone 281-555-0450

Repair Estimate

Estimate number:	EST-520038
Estimate date:	2023-02-17
Customer:	Rhonda Cole
Phone:	346-555-1509
Insurance claim:	C-1356
Vehicle:	2023 Toyota Camry
VIN:	6KE8FG5MXAE4X3118
License plate:	9C 8H8SOE

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$874.89
Right front door shell	1	$927.95
Hood panel	1	$748.86
Body labor	25.9 hrs	$1,758.89
Paint and materials		$1,067.80
TOTAL		$5,378.39

Appraiser remarks

The rear bumper cover is cracked across its lower center, the left tail lamp housing is shattered, and the trunk lid shows a crease running toward the driver side. The pattern of the damage lines up with the impact reported at the scene, and nothing I found points to older harm on this vehicle. The plan is to replace the bumper cover and tail lamp assembly, repair and refinish the trunk lid, and recalibrate the parking sensors. The labor hours listed fit the scope of this work, and the invoices submitted contain no repeated line items. I recommend approving the estimate as written.