Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-169537
Estimate date:	11-13-24
Customer:	Adam Fowler
Phone:	832-555-1961
Insurance claim:	C-1358
Vehicle:	2023 Ford F-150
VIN:	F2RU518X4LAHT4842
License plate:	193 0647

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,226.59
Left quarter panel	1	$1,073.35
Front bumper cover	1	$893.20
Body labor	27.3 hrs	$1,855.18
Paint and materials		$764.93
TOTAL		$5,813.25

Appraiser remarks

Rear bumper cover cracked across the left corner, with the left quarter panel creased and the tail lamp assembly broken. The pattern of contact is consistent with the low-speed impact reported in the parking lot, and the location and direction of the marks line up with the account given. No prior damage to this vehicle is known to us, and the paint and panel edges show no older repair work. The plan is to replace the bumper cover and tail lamp, pull and refinish the quarter panel, and recalibrate the parking sensors. The labor hours listed are reasonable for this scope, and the invoices we reviewed show each charge once with no duplicated entries.