Guerrero Auto Body

83242 Brian Turnpike Suite 994
League City, TX
Phone 713-555-7464

Repair Estimate

Estimate number:	EST-640552
Estimate date:	2024-03-05
Customer:	Jillian Rasmussen
Phone:	281-555-5623
Insurance claim:	C-1360
Vehicle:	2010 Chevrolet Malibu
VIN:	UT1BEM0638B5F7921
License plate:	KCA-2719

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$638.36
Headlamp assembly	1	$614.44
Hood panel	1	$329.70
Body labor	20.0 hrs	$1,362.05
Paint and materials		$655.03
TOTAL		$3,599.58

Appraiser remarks

The vehicle shows damage to the front left corner, including a cracked bumper cover, a bent headlamp bracket, and a crushed fender with a damaged wheel liner. The pattern matches the impact described for a left turn into oncoming traffic, and the panels affected are consistent with that direction of force. The rpeair plan calls for replacing the bumper cover and headlamp assembly, straightening the fender, and refinishing the adjoining panels for color match. Labor hours are in line with the work required for this damage. The invoices reviewed contain no duplicated line items or repeated charges. Nothing in the file suggests earlier damage to this vehicle in the same area. Repairs are recommended as shown.